



TECHNICAL & SAFETY COMMITTEE INTERNATIONAL PARACHUTING COMMISSION (FAI)

Technical & Safety Bulletin No.	2/2007	W.N. 13
Date of Issue	12 December 2007	
Subject Matter 1	<p>Aerodyne Research Service Bulletin SB271107, dated 27 November 2007, 2 pages.</p> <p>Concerning – All ICON harness/Container systems, Part No. P120, manufactured after and including 01 September 2007</p> <p>Reason – Damage to grommets on an ICON contained; damage having been caused by the grommet press.</p> <p>Status of Bulletin – Precautionary. The incident may have been an isolated one but as a precautionary measure Aerodyne is recommending that all grommets on systems noted above be inspected.</p> <p>Attached – A copy of the Aerodyne Service Bulletin SB271107, in PDF format, is appended with this IPC Safety Bulletin.</p>	

**Thanks to the Austrian Aero Club for forwarding this safety bulletin to the IPC
Technical & Safety Committee**

Technical and Safety Bulletins issued by the Technical & Safety Committee of the International Parachuting Commission (FAI) are issued as a guide and help to parachuting nations. The bulletins are advisory and there is no direct or implied criticism of any manufacturer or product intended. The bulletins result from:-

- 1 An incident or experience in the field being reported.*
- 2 The issue of a notice by a manufacturer or by a National Parachuting Organisation. In the case of equipment being the subject of the bulletin the reader is advised to check with the manufacturer regarding the current status or position of that equipment.*

Technical & Safety Committee of IPC, IPC and FAI accept no liability for the use or misuse of any information contained in this bulletin. The reader assumes all liability.