



SERVICE BULLETIN

DATE:	July 21, 1995	SERVICE BULLETIN #	SB-1527	# OF PAGES:	1
SUBJECT:	'94 TALON RSL POCKET MOD				
STATUS:	OPTIONAL				

IDENTIFICATION:

All '94 Talons manufactured prior to May 25, 1995 including Classic Pro models.

BACKGROUND:

Experience has shown that the RSL pocket configuration used prior to this change sometimes allowed the RSL lanyard to pop out of the bottom pocket during normal use.

SERVICE BULLETIN:

If your Talon or Classic Pro experiences a loose RSL lanyard and you wish to continue using the RSL , the system may be modified according to PMP-1241. A factory kit and procedure is available at no charge from the Rigging Innovations Inc. but must be installed by a Master Rigger.

COMPLIANCE DATE:

NONE: This is optional at the owner's discretion or as needed.

AUTHORITY:

SANDY R. REID, PRESIDENT
Rigging Innovations Inc.
P O Box 86, ELOY AZ 85231, USA
Telephone: 520-466-2655
FAX: 520-466-2656

DISTRIBUTION:

All registered owners affected by the Service Bulletin.
All Rigging Innovations Dealers.
All Parachuting Publications.
National Aero Clubs, Parachuting Section.
Military Parachute Organizations.