AERAZUR
2 rue Maurice Mallet
92130 Issy les Moulineaux
Tél : +33 (0)1 41 23 23 23
Fax : +33 (0)1 46 48 83 41

SERVICE BULLETIN

Title : Reserve Canopy Control
Titre: Contrôle des voilures de secours

BS 25-63-46
Date: 12/12/2008

Block 1 Technical Background

a) Applicability : All Parachutes de France's reserve canopies.

b) Reason : Control of reserve canopies before next packing.

c) Description : During the packing of a reserve canopy (training parachute in service in the French Army), the rigger observed that a ring used to stop the riser was missing.

- ⇨ All available canopies of the same model were controlled by French Army.
- ⇨ Control process was audited on production plant.
- ⇨ All canopies in supplier stock were controlled.

Considering that no new case was found, it was concluded it was a particular and single case.

d) Compliance : As a precaution, at the next periodic inspection/packing of the reserve (all types), it is recommended to verify that all slider stops are present and to mention this control on canopy official documents.

e) Approval : The technical content of this service bulletin has been approved by Aerazur according to Part 21.

f) Labour : Senior or master rigger or equivalent according to the local regulation.

g) Weight and balance : Non applicable.

h) Reference document : Non applicable.

i) Concerned publication : User manual of concerned canopy.

j) Interchangeability : Non applicable.

Block 2 Information about equipment

a) Material : Non applicable.

b) Supplier : AERAZUR / Parachutes de France, 2 rue Maurice Mallet,
92130 Issy les Moulineaux, France
E-mail : infopdf@zodiac.com
Tel : +33 (0)1 41 23 23 23,
Fax : +33 (0)1 46 48 83 41.

Block 3 Accomplishment instructions

Non applicable.

Block 4 Diffusion

DGAC – GSAC – FFP – ARZ – Dealers – Users.