

RIGGING ADVISORY CIRCULAR

Issue Date: 01 July 1986

RAC No. 410 Rev. A

<u>SUBJECT</u>	CENTAURUS RECALL
<u>STATUS</u>	Mandatory
IDENTIFICATION	Centaurus Harness/Container Date of manufacture: 11 th May 1985 to 18 th September 1985
MANUFACTURER ADVISORY	North American Aerodynamics Inc. has recalled all Centaurus Harness/Container systems manufactured between 1 May 1986 to 18 September 1986.
	These assemblies are recalled because they may have MS70101 adjustable adaptors with sharp edges on the inside shoulder.
	These assemblies may not be jumped until the MS 70101 on the chest strap has been replaced, or a buffer inserted to protect the Type 8 webbing which attaches it to the harness.
	NAA will perform the work free of charge.
<u>AUTHORITY</u>	North American Aerodynamics, Inc. through Parachutist Magazine June '86.
DISTRIBUTION	All APF Parachute Maintenance Manual Owners