

## **RIGGING ADVISORY CIRCULAR**

Issue Date: 18 August 1993

RAC No. 425 Rev. A

SUBJECT:	CLOSING LOOPS AND BACKING WASHER
STATUS:	ADVISORY
<b>IDENTIFICATION:</b>	All parachutes.
<u>BACKGROUND:</u>	A recent incident report identified a badly worn closing loop with damaged fibres at the end nearest the knot The wear to the loop was caused by the sharp edges of the washer. <i>Inspection of the closing loop is normally confined to the visible part of the 'formed eye' that wears from contact with the ripcord pin and/or pull-up cord.</i>
<u>APF ADVISORY:</u>	At each scheduled reserve inspection remove the closing loops from both the reserve and main containers and determine if wear exists. Replace loops <i>(and washers)</i> when wear has been caused from the sharp edges of the washer.
	Marine
COMPLIANCE DATE:	Next scheduled service.
AUTHORITY:	Director Rigging.
DISTRIBUTION:	All APF Packer A's