



MarS a.s., Okružní II 239, 569 43 Jevíčko
Czech Republic

PRODUCT
SERVICE
BULLETIN

C

PRODUCT SERVICE BULLETIN

1. Issue Date : **11 November 2013**
2. Bulletin Number : **10/11/2013**
3. Subject : **Error Messages - Inspection of m2 (AAD)**
4. Compliance : **Mandatory**
5. Identification : m2 Safety Devices with serial numbers:
SN: 001330 – 001379; SN: 001384 – 001446
SN: 001556 – 001727

6. Background:

During operation of m2 Safety Devices to date, there have been seven (7) reported cases of "Error No. 0" or "Error No. 1" being displayed on the units. Further, it was not possible to eliminate the error indication by switching the unit off and on again. Inspection by the manufacturer disclosed a device sensor error. The error is repairable by the manufacturer in affected units.

7. Compliance:

The affected unit(s) must be sent to the manufacturer for inspection, repair or exchange for a new device. All costs related to the manufacturer's inspection, repair or replacement, and return shipping to the user will be covered by the manufacturer.

8. Compliance Date:

When the unit displays the error, or for a unit covered by this Service Bulletin, even if no error has been detected and displayed on the unit, it may be sent immediately.

9. Authority:

Ing. Jaroslav Sedlák
Technical Department Manager
MarS a.s.

Stamp and signature:



Distribution of this Mandatory Product Service Bulletin shall include, but is not limited to:

- All identified owners of m2 Safety Devices with affected serial numbers
- All m2 Safety Device dealers
- Parachute Industry Association
- United States Parachute Association
- All identified parachuting publications
- All identified parachuting federations and associations
- All National Aero Clubs, parachuting section
- IPC Technical Committee