

Product Service Bulletin

Issue Date: 02/21/2007

Bulletin Number: PSB-3

Subject: Vigil Cutters with Plastic Insert

Status: Advisory

Identification:

Vigil AAD, All Cutters with Plastic Insert made before August 2006. Part Number: 9582006 Made Before August 2006

Background:

Cutters have been found in the field with damaged plastic inserts that have in turn damaged the closing loops. If the damage is severe enough, it is possible for the reserve-closing loop to sustain damage.

In regards of the FFP Bulletin #122:

Until now all the reported damaged cutters with plastic insert have been identified, recalled and replaced.



Service Bulletin:

Inspect the plastic insert for signs of damage. At the same time inspect the loop for signs of wear and damage from the cutter frame.

If damage is found, please contact your dealer, Vigil AAD Brussels or Vigil USA for advice and/or eventual cutter replacement.

Compliance Date:

Next repack cycle.

Authority:

Yann Bronnec / Jo Smolders P.R. Manager / President

AAD sa/nv

Bld A.Reyers, 193 1030 Brussels – Belgium – Europe +32 2 732 65 52 – Fax : +32 2 736 06 27 www.vigil.aero - yann@vigil.aero - info@vigil.aero

Vigil USA LLC 1645 Lexington Avenue Deland, FL 32724 +386 736 8464 – Fax : +386 736 8468 www.vigil.aero - candace@vigil.aero





<u>OK</u>



NOT OK



<u>OK</u>



NOT OK



<u>OK</u>









New Full Inox Replacement Cutter (From August 2006)

The Distribution list shall include but is not limited to:

- All registered owners.
- All AAD dealers.
- Manufacturers
- Parachute Industry Association.
- All Parachuting publications.
- All National Aero Clubs, Parachuting Section.
- IPC Technical Committee.
- Military Parachute Organizations.