



MarS a.s., Okružní II 239, 569 43 Jevíčko

CZECH REPUBLIC

SERVICE
BULLETIN

C

SERVICE BULLETIN no. 09/10/2013

Interruption of diving performance

1. **SUBJECT MATTER:** Parachute sets configured in the composition below:
- parachute container OP-087
 - parachute container OP-093 and OP-093/01
 - parachute container OP-095 T
 - parachute container OP-103
 - MPAAD security device;

WARNING:

If the parachute sets above are completed **without device MPAAD**, or include different security device (e.g. **m2, CYPRES, VIGIL**), the interruption **does not relate** to the parachute sets.

If MPAAD device is installed and not used, correct function of the parachute container remains maintained – during the reserve parachute opening by means of rip cord of the reserve parachute.

2. **REASON:** Exceptional accident on 19. 10. 2013 by airport Inowroclaw EPIN in Poland. The accident cause is still under investigation.
3. **MEASURES:** **Until further** notice, stop the diving performance on the above specified sets.
4. **VALIDITY:** From date of bulleting issue:
5. **DATE OF ISSUE:** In Jevíčko on 24. 10. 2013

Ing. Jaroslav Sedlák – Technical Department Manager
MarS a.s.

Stamp and signature:

