

## **RIGGING ADVISORY CIRCULAR**

Issue Date: 01 November 1986

RAC No. 307 Rev. A

Page 1 of 1

| SUBJECT:                                | PIONEER RESERVE CONVERSION TO 4 RISERS   |  |
|---|--|--|
| STATUS:                                 | OPTIONAL   |  |
| <b>IDENTIFICATION:</b>                  | Model  | Canopy Part No.                                  |
|   | K-20<br>K-22<br>Super 22 (Low Speed category)<br>Super 22 (Standard category)<br>K-26 Conical  | 5275-1<br>5418-1<br>5050-1<br>5050-501<br>5400-1 |
| <u>MANUFACTURER</u><br><u>ADVISORY:</u> | <ul><li>The above parachutes may be converted for use with four risers.</li><li>The conversion must be performed by a Rigger B or foreign equivalent.</li><li>Slide lines one-by-one and in order from one existing separable link onto two No.6 Maillon Rapide Links, with equal number of lines on both links. Repeat with remaining connector link.</li><li>Check for proper rigging and direction of flight.</li></ul> |  |
|   |  |  |
|   |  |  |
|   |  |  |
|   | Note that risers many need to be rapide links.   | e modified if not compatible with                |
| AUTHORITY:                              | Pioneer Parachute Co.  |  |
| DISTRIBUTION:                           | PMM Purchaser  |  |
|   |  |  |
|   |  |  |