



RIGGING ADVISORY CIRCULAR

Issue Date: 01 November 1985

RAC No. 405 Rev. A

SUBJECT WARP III MODIFICATION ADVISORY


STATUS Mandatory.

BACKGROUND National Parachutes Inc, have issued a Safety Bulletin concerning their Warp 3 Piggybacks manufactured before July 1984.

Apparently a few rigs have been found where the first pin on the reserve container managed to get jammed in the housing before the 2nd pin was clear of the locking loop.

MANUFACTURER ADVISORY

The manufacture recommends moving the reserve housing to the position shown in the following diagram.



AUTHORITY National Parachutes Inc.

EFFECTIVE DATE Immediately.

DISTRIBUTION AllAPF Packers and Riggers
All Manual holders