



RIGGING ADVISORY CIRCULAR

Issue Date: 01 December 1991

RAC No. 814 Rev. A

SUBJECT: ROOCHUTES 1" WIDE MAIN RISER RECALL

STATUS: MANDATORY

IDENTIFICATION: All main risers manufactured by Roochutes Australia Pty Limited for the Woomera harness/container from 1" wide type XVII black webbing and using a size #0 grommet for the final 3-ring loop.

BACKGROUND: During periodic inspection, a Woomera was found to have a loose #0 spur grommet on one riser. It is possible that this defect could hinder the safe operation of the 3-ring mechanism.

MANUFACTURER'S ADVICE: All 1" wide type XVII black main risers manufactured by Roochutes Australia Pty Limited are to be withdrawn from service immediately.

The risers should be forwarded to Roochutes for inspection and replacement of the #0 grommet.

This modification will be carried out free of charge.

APF POLICY: As manufacturer's advice

EFFECTIVE DATE: Immediately.

AUTHORITY: Manufacturer's advice:
Roochutes Australia Pty Limited
P.O. Box 125
Wynnum QLD 4178
phone: 07-393 4409

APF Policy:
APF Director, Riggers

DISTRIBUTION: RAC Subscribers
APF Riggers and Packers