COMMONWEALTH OF AUSTRALIA CIVIL AVIATION SAFETY AUTHORITY SCHEDULE OF AIRWORTHINESS DIRECTIVES

Parachute Equipment

$\Lambda D/D \Lambda D \Lambda / E$	Parachutas Da Franca Connector Links	10/05
AD/PARA/5	Parachutes De France - Connector Links	10/95

Applicability: Parachutes De France emergency parachutes P512()01 delivered after 21 June 1994,

and with the following serial numbers:

DE039 to DE046 DF001 to DF024 DG001 to DG017

DH001 to DH006 DJ001 to DJ019 DM001 to DM025

EC001 to EC031 ED001 to ED025 EE001 to EE019

Requirement: Inspect the connector links between the canopy and the harness container, and verify

full thread engagement and torque in accordance with the manufacturer's instructions.

Note: DGAC AD 95-131(AB) and Parachutes De France ASB P512-25-002 refer.

Compliance: Prior to further use after 14 September 1995.

Background: During a periodic inspection a parachute was found with loose connector links.