



**TECHNCIAL & SAFETY COMMITTEE
INTERNATIONAL PARACHUTING COMMISSION (FAI)**

Technical & Safety Bulletin No.	4/2005	W.N. 4
Date of Issue	13 December 2005	
Subject Matter	Sun Path Javelin Containers with RED CORDURA 1000d RESERVE CONTAINERS, WITH A DATE OF MANUFACTURE BETWEEN FEBRUARY 2002 AND OCTOBER 2002 ONLY.	
Origin for material/bulletin	Sun Path Products Inc. Service Bulletin# SPSB004 Date – 12 December 2005	
Equipment Manufacturer	Sun Path Products Inc.	

Technical and Safety Bulletins issued by the Technical & Safety Committee of the International Parachuting Commission (FAI) are issued as a guide and help to parachuting nations. The bulletins are advisory and there is no direct or implied criticism of any manufacturer or product intended. The bulletins result from:-

- 1 An incident or experience in the field being reported.*
 - 2 The issue of a notice by a manufacturer or by a National Parachuting Organisation.*
- In the case of equipment being the subject of the bulletin the reader is advised to check with the manufacturer regarding the current status or position of that equipment.*

Area of concern	To quote from the Sun Path Products Inc. Service Bulletin, referenced above “The use of a roll of Red 1000d Cordura, received by Sun Path Products in 2002, and which may have had a substandard urethane coating. This substandard coating, where used in a manner where it has a relationship with F111 fabric, may cause the two layers to ‘stick together”.
Sun Path Service Bulletin# SPSB004	Sun Path Service Bulletin# SPSB004 is appended.
Compliance date	IMMEDIATELY, BEFORE NEXT USE – See Sun Path SPSB004 for compliance details.