No.:

Safety Bulletin

No.: 1/2010 from 15.01.2010

Publisher Fallschirmbau Buchsein/Hermesdorf GbR

Von-der-Recke-Str. 12 58300 Wetter/Ruhr

Applicability Safety Parachutes series Thinback T104 and Slimpack T204, serial

numbers (s/n) from 41495 to 41776 inclusive.

Note: These emergency parachutes have been manufactured between

April 4th 2008 and January 15th 2010.

Reason During tensile testing on parachute primary actuation devices the ripcord

pins have been found to be insufficiently fixed to the ripcord cable. An internal process review has revealed that the pins installed on the primary actuation device of Emergency Parachutes series Thinback T104 and Slimpack T204 may not been fixed properly to the ripcord cable.

This condition, if not corrected, could lead the ripcord to be pulled out of the cable end pin and prevent the pilot chute from opening and this prevent the

main parachute from being pulled out of its storage pack. The reason described above requires the inspection and the

rework by the manufacturer of the identified ripcord assembly on the

affected emergency parachutes.

Actions 1. all affected emergency parachutes of this series within the

serial No's above are grounded

2. all ripcords of the both safety parachute typs Thinback T104 and Slimpack T 204 must be tested by the manufacuter and will be back to service after reconditioning. A sign should be at "Fallschirm Betriebs- und Packnachweis" at page 10 and 11: Vorsteckstifte überprüft.

date, sign and stamp. At ripcord handle will be a stamp H1

Execution Take out each ripcord from the emergency parachutes and the smale book

"Fallschirm Betriebs- und Packnachweis" a suitable address for

back mailing and postage into a padded A5 envelope

and send it to

Rettungsfallschirm-Service

Peter Hermesdorf Hasenböge 18 21514 Klein Pampau

Germany

For any questions concerning the technical content of the requirements please contact:

Horst Buchsein 02335/69905 mailto <u>B.Buchsein@Buchsein.eu</u>
Peter Hermesdorf 04155/3768 mailto: peter@hermesdorf.de

Wetter, den 15.Jan. 2010

Hermasdorf